



MATERIAL GROUP	HARDNESS HRC		Size (mm)									
			1.0	1.2	1.5	2.0	2.5	3.0	3.5	4.0	4.5	
P	13 14	< 35	v_c (m/min)	84	85	88	91	101	105	113	119	122
			n	26800	22500	18750	14450	12800	11150	10300	9450	8660
			f_z	0.002	0.003	0.003	0.005	0.0008	0.007	0.011	0.015	0.017
			f (mm/min)	240	250	255	280	300	320	445	570	585
H	15 16	35-45	v_c (m/min)	51	51	53	59	64	66	70	73	74
			n	16080	13500	11250	9450	8200	6950	6360	5780	5250
			f_z	0.002	0.003	0.003	0.004	0.006	0.007	0.011	0.015	0.017
			f (mm/min)	145	150	115	170	185	200	275	350	355
	16 16	45-55	v_c (m/min)	34	34	35	40	41	40	43	46	47
			n	10720	9000	7500	6300	5250	4200	3940	3680	3290
			f_z	0.001	0.001	0.002	0.002	0.003	0.004	0.004	0.004	0.005
			f (mm/min)	45	45	45	50	55	60	60	60	65
M	21 22 23		v_c (m/min)	42	42	44	50	54	54	58	61	62
			n	13400	11250	9380	7880	6830	5780	5310	4850	4400
			f_z	0.002	0.003	0.003	0.004	0.006	0.007	0.011	0.014	0.016
			f (mm/min)	120	125	130	140	155	170	225	280	290
K	31 32 33 34		v_c (m/min)	84	85	88	91	101	105	113	119	122
			n	26800	22500	18750	14450	12800	11150	10300	9450	8660
			f_z	0.002	0.003	0.003	0.005	0.0008	0.007	0.011	0.015	0.017
			f (mm/min)	240	250	255	280	300	320	445	570	585

v_c - cutting speed (m/min)
 n - RPM (rev/min)
 f_z - feed rate (mm/tooth)
 f - feed rate (mm/rev)
 z - No. of teeth
 a_p - axial depth of cut
 a_e - radial depth of cut


To calculate RPM from cutting speed: $n = \frac{v_c \times 1000}{\pi \times \phi}$

To calculate cutting speed from RPM: $v_c = \frac{n \times \pi \times \phi}{1000}$

All recommendations are based on ideal machining conditions. Adjustments may need to be made according to your set-up. The recommendations for speeds, feeds and other parameters presented in this chart are nominal recommendations and should be considered only as good starting points.



MATERIAL GROUP	HARDNESS HRc		Size (mm)									
			5.0	5.5	6.0	6.5	7.0	7.5	8.0	8.5	9.0	
P	13 14	< 35	v_c (m/min)	124	128	131	133	134	134	132	132	132
			n	7880	7410	6950	6530	6100	5680	5250	4980	4660
			f_z	0.019	0.021	0.024	0.026	0.028	0.031	0.034	0.035	0.035
			f (mm/min)	600	630	660	675	685	700	710	685	660
H	16 16	35-45	v_c (m/min)	74	77	79	80	81	80	79	80	80
			n	4730	4460	4200	3940	3680	3410	3150	2990	2830
			f_z	0.019	0.022	0.024	0.026	0.027	0.029	0.03	0.03	0.03
			f (mm/min)	360	385	410	405	395	390	380	360	340
	16 16	45-55	v_c (m/min)	46	47	47	49	51	52	53	53	57
			n	2900	2700	2500	2400	2300	2200	2100	2000	1900
			f_z	0.008	0.007	0.008	0.009	0.01	0.012	0.013	0.013	0.013
			f (mm/min)	70	75	80	90	95	105	110	105	100
M	21 22 23		v_c (m/min)	62	65	67	68	68	68	66	66	67
			n	3950	37550	3550	3320	3090	2860	2630	2490	2360
			f_z	0.019	0.021	0.023	0.025	0.026	0.03	0.033	0.034	0.034
			f (mm/min)	300	315	330	335	340	345	350	340	325
K	31 32 33 34		v_c (m/min)	124	128	131	133	134	134	132	132	132
			n	7880	7410	6950	6530	6100	5680	5250	4980	4660
			f_z	0.019	0.021	0.024	0.026	0.028	0.031	0.034	0.035	0.035
			f (mm/min)	600	630	660	675	685	700	710	685	660



v_c - cutting speed (m/min)
 n - RPM (rev/min)
 f_z - feed rate (mm/tooth)
 f - feed rate (mm/rev)
 z - No. of teeth
 a_p - axial depth of cut
 a_e - radial depth of cut

$$\text{To calculate RPM from cutting speed: } n = \frac{v_c \times 1000}{\pi \times \phi}$$

$$\text{To calculate cutting speed from RPM: } v_c = \frac{n \times \pi \times \phi}{1000}$$

All recommendations are based on ideal machining conditions. Adjustments may need to be made according to your set-up. The recommendations for speeds, feeds and other parameters presented in this chart are nominal recommendations and should be considered only as good starting points.



MATERIAL GROUP	HARDNESS HRC		Size (mm)								
			9.5	10.0	11.0	12.0	14.0	16.0	18.0	20.0	
P	13 14	< 35	v_c (m/min)	130	128	130	129	136	138	137	132
			n	4370	4080	3750	3430	3090	2750	2430	2100
			f_z	0.036	0.037	0.038	0.038	0.038	0.038	0.038	0.038
			f (mm/min)	635	640	565	520	465	420	365	320
H	15 15	35-45	v_c (m/min)	79	79	79	79	84	85	85	84
			n	2660	2500	2300	2100	1900	1700	1510	1330
			f_z	0.03	0.03	0.03	0.03	0.03	0.03	0.03	0.03
			f (mm/min)	320	300	275	250	225	205	180	160
	15 15	45-55	v_c (m/min)	54	53	55	55	57	57	56	53
			n	1800	1700	1580	1450	1290	1130	990	850
			f_z	0.013	0.013	0.013	0.014	0.014	0.013	0.013	0.012
			f (mm/min)	95	90	85	80	70	60	50	40
M	21 22 23	v_c (m/min)	67	66	66	64	68	69	68	66	
		n	2230	2100	1900	1700	1540	1380	1210	1050	
		f_z	0.035	0.036	0.036	0.035	0.036	0.036	0.036	0.036	
		f (mm/min)	315	300	270	240	220	200	175	150	
K	31 32 33 34	v_c (m/min)	130	128	130	129	136	138	137	132	
		n	4370	4080	3750	3430	3090	2750	2430	2100	
		f_z	0.036	0.037	0.038	0.038	0.038	0.038	0.038	0.038	
		f (mm/min)	635	640	565	520	465	420	365	320	

v_c - cutting speed (m/min)
 n - RPM (rev/min)
 f_z - feed rate (mm/tooth)
 f - feed rate (mm/rev)
 z - No. of teeth
 a_p - axial depth of cut
 a_e - radial depth of cut

To calculate RPM from cutting speed: $n = \frac{v_c \times 1000}{\pi \times \phi}$

To calculate cutting speed from RPM: $v_c = \frac{n \times \pi \times \phi}{1000}$

All recommendations are based on ideal machining conditions. Adjustments may need to be made according to your set-up. The recommendations for speeds, feeds and other parameters presented in this chart are nominal recommendations and should be considered only as good starting points.