

Miniature Thread Mills <62HRc



Material Group			$v_c$ (m/min)	$f_z$ (mm/tooth)	
				Cutter diameter $\leq \phi 6.0$	Cutter diameter $> \phi 6.0$
<b>P</b>	11	Magnetic soft steels	100 (80-120)	0.03 (0.02 - 0.04)	0.05 (0.04 - 0.06)
	12	Structural steels, case carburizing steels			
<b>H</b>	15	Hardened steels 45 - 50HRc	45 (25-70)	0.04 (0.03 - 0.05)	0.06 (0.05 - 0.07)
	16	Hardened steels 51 - 55HRc	40 (25-60)	0.03 (0.02 - 0.04)	0.05 (0.04 - 0.06)
<b>M</b>	15	Hardened steels 56 - 62HRc	35 (25-50)	0.02 (0.01 - 0.03)	0.04 (0.03 - 0.05)
	21	Free machining stainless steel	60 (40-80)	0.03 (0.02 - 0.04)	0.05 (0.04 - 0.06)
<b>K</b>	22	Austenitic stainless steel			
	23	Ferritic, Ferritic+Austenitic,Martensitic			
<b>S</b>	31	Grey cast iron soft	75 (50-100)		
	32	Grey cast iron hard		0.04 (0.03 - 0.05)	0.06 (0.05 - 0.07)
	33	Nodular graphite cast iron <200HB			
	34	Nodular graphite cast iron <300HB			
<b>Titanium</b>	41	Titanium, unalloyed	40 (20-60)	0.025 (0.02 - 0.03)	0.04 (0.03 - 0.05)
	42	Titanium, alloyed <270HB			
	43	Titanium, alloyed <350HB			
<b>Heat resisting alloys</b>	51	Nickel, unalloyed	40 (20-60)	0.025 (0.02 - 0.03)	0.04 (0.03 - 0.05)
	52	Heat resisting alloys <270HB			
	53	Heat resisting alloys <350HB			

$v_c$  - cutting speed (m/min)

n - RPM (rev/min)

$f_z$  - feed rate (mm/tooth)

f - feed rate (mm/rev)

z - No. of teeth

$f_1$  - feed at cutting edge

$f_2$  - feed at centre line

D - thread major diameter

$$\text{To calculate RPM from cutting speed: } n = \frac{v_c \times 1000}{\pi \times \phi}$$

$$\text{To calculate feed per revolution: } f_1 = n \times f_z \times z$$

$$\text{To calculate feed at tool centre line: } f_2 = \frac{f_1 \times (D - \phi)}{D}$$

All recommendations are based on ideal machining conditions. Adjustments may need to be made according to your set-up. The recommendations for speeds, feeds and other parameters presented in this chart are nominal recommendations and should be considered only as good starting points.