

Through Coolant and Solid Thread Mills



Material Group		vc (m/min)	fz (mm/tooth)	
			Cutter diameter ≤ ø8.0	Cutter diameter > ø8.0
P	11	100 (80-120)	0.03 (0.02 - 0.04)	0.07 (0.04 - 0.1)
	12			
	13			
	14			
H	15	80 (60-100)	0.03 (0.02 - 0.04)	0.07 (0.04 - 0.1)
M	21	60 (40-80)	0.015 (0.01 - 0.02)	0.04 (0.02 - 0.06)
	22			
	23			
K	31	75 (60-100)	0.03 (0.02 - 0.04)	0.07 (0.04 - 0.1)
	32			
	33			
	34			
S	41	40 (20-60)	0.015 (0.01 - 0.02)	0.04 (0.02 - 0.06)
	42			
	43			
	51			
	52			
	53	40 (20-60)	0.015 (0.01 - 0.02)	0.04 (0.02 - 0.06)
N	61	200 (100-300)	0.05 (0.03 - 0.07)	0.075 (0.05 - 0.1)
	62			
	63			
	64			
	71			
	72			
	73			
	74	200 (100-300)	0.05 (0.03 - 0.07)	0.075 (0.05 - 0.1)

► For programming details see page 130

vc - cutting speed (m/min)
 n - RPM (rev/min)
 fz - feed rate (mm/tooth)
 f - feed rate (mm/rev)
 z - No. of teeth
 fi - feed at cutting edge
 fc - feed at centre line
 D - thread major diameter

$$\text{To calculate RPM from cutting speed: } n = \frac{v_c \times 1000}{\pi \times \phi}$$

$$\text{To calculate feed per revolution: } f_i = n \times f_z \times z$$

$$\text{To calculate feed at tool centre line: } f_c = \frac{f_i \times (D - \phi)}{D}$$

All recommendations are based on ideal machining conditions. Adjustments may need to be made according to your set-up. The recommendations for speeds, feeds and other parameters presented in this chart are nominal recommendations and should be considered only as good starting points.